



South Hedland Aquatic Centre Redevelopment

- The Town has received the results from the statutory water samples taken on Monday 29 April and Wednesday 1 May 2013.
- The results from the Monday test showed filters one and three failing to achieve compliance.
- The results from Wednesday 1 May showed filters one, two and three failing to achieve compliance.
- Due to recurring failures of the filter backwash samples, the project contractor has been requested to remain on site to remediate and monitor the water treatment plant filters, until such times as the facility reopens to the public and the filters are operating as they should.
- Samples will be taken today, and on Wednesday 8 May 2013.



Principal Partners



Department of Regional Development and Lands



Supporting Partners



Department of Sport and Recreation

Australian Government
Department of Regional Australia,
Regional Development and Local Government



Marquee Park Splash and Play, South Hedland

- The Marquee Park kiosk was broken into last night (Sunday 5 May) with considerable damage to the vending machines.
- Vandals also caused damage to 10 sprinklers around the park area.
- The water-play area at Marquee Park Splash and Play reopened to the community on Sunday 5 May 2013.
- The computer issues with the water-treatment plant are now resolved.
- Installation of CCTV has commenced and is expected to be complete by the end of the month.



Principal Partners



Department of Regional Development and Lands

Department of Housing



Supporting Partners

